gs) 184 D



				1911 kg	
O COA POTENTIAL HAZARDO	REGION	SITE NUMBER (to be 44-			
IDENTIFICATION AND PRELIMINARY ASSESSMENT				TX11088	
NOTE: This form is completed for each potential hazardous submitted on this form is based on available records and may and on-site inspections. GENERAL INSTRUCTIONS: Complete Sections I and III three Assessment). File this form in the Regional Hazardous Wast Agency; Site Tracking System; Hazardous Waste Enforcement	be updated on survey with X as comple to Log File and su	tely as possible be	a result of	of additional inquiries	
	DENTIFICATION		DØ	00764498	
BHT - Site 6 at Plant 5		other identifier)	- "		
C. CITY	D. STATE	360 at Avenu			
Grand Prairie	TX	75050	Dallas		
G. OWNER/OPERATOR (If known) 1. NAME Bell Helicopter Textron, Inc. (Owner: To				PHONE NUMBER 7) 280-3617	
H. TYPE OF OWNERSHIP	INICIPAL X 5.	PRIVATE6	UNKNOWN		
location of two unlined settling lagoon J. HOW IDENTIFIED (1.0 citizen's complaints, OSHA citations, etc.	S.			K. DATE IDENTIFIED	
Self-notification under CERCLA			1/25/82		
L. PRINCIPAL STATE CONTACT					
1. NAME		Z. TELEPHONE NUMBER			
Daniel L. Scheppers	(512) 475-1344				
II. PRELIMINARY ASSESS	MENT (complete	this section (ast)			
A. APPARENT SERIOUSNESS OF PROBLEM 1. HIGH 2. MEDIUM 3. 1.0% X. 4. NO	DNE5	UNKNOWN			
B. RECOMMENDATION				CUDEDEL	
X 1. NO ACTION NEEDED (no hesard)	2. IMME	DIATE SITE INSPEC	TION NES	SUPERFUND FILE	
a. TENTATIVALY SCHEDULED FOR:	b. WIL	L BE PERFORMED	BY:	OCT 2 1 1992	
b. WILL SE PERFORMED SY:	4. SITE	INSPECTION NEED	ED (low pr	TOTAL PROPERTY OF THE PROPERTY	
C. PREPARER INFORMATION		EPHONE NUMBER		1 3. CA FE (MO., Cay, & yr.)	
Bob Davis, Engineering-Science, Inc.		2) 477-9901		11/21/83	

III. SITE INFORMATION

A. SITE STATUS

1. ACTIVE (Those industrial or municipal sites which are being used for waste treatment, storage, or disposon a continuing basis, even if intro-quently.)

32046'25"

X 2 INACTIVE (Those sites which no longer receive (Those sites that include such incidents like "midnight dumping!" where weates.)

. IS GENERATOR ON SITE?

C. AREA OF SITE (In ecree)

☐ 1. NO

0.3

T2970-2 (14-79)

X 2 YES (epecity generator's low-digit SIC Code): 3728

D. IF APPARENT SERIOUSNESS OF THE IS HIGH, SPECIFY COORDINATES 1. LONGITUDE (det .-- mir 1. LATITUDE (deg-min-sec.) 97003'30"

E. ARE THERE BUILDINGS ON THE SITE?

Cor inue On Reverse



EPA Form T2070-2 (10-79)

PAGE 2 OF 4

Continue On Page 3

V. WASTE RELATED INFORMATION (continued)
3. LIST SUBSTANCES OF GREATEST CONCERN WHICH MAY BE ON THE SITE (place in descending order of hexard).

Hexavalent chromium

4 ADDITIONAL COMMENTS OR NARRATIVE DESCRIPTION OF SITUATION KNOWN OR REPORTED TO EXIST AT THE SITE.

See Attachment A

VI. HAZARD DESCRIPTION						
A. TYPE OF HAZARD	B. POTEN- TIAL HAZARD (mark 'X')	C. ALLEGED (NCIDENT (mark 'X')	D. DATE OF INCIDENT (mo.,dey,yr.)	E. REMARKŠ		
1. NO HAZARD			The second section			
2. HUMAN HEALTH						
3. NON-WORKER INJURY/EXPOSURE						
4. WORKER INJURY						
5. CONTAMINATION OF WATER SUPPLY				· ·		
6. CONTAMINATION OF POOD CHAIN						
7. CONTAMINATION OF GROUND WATER	x			Some subsurface migration of contaminants may have occurred prior to removal of wastes.		
. CONTAMINATION OF SURFACE WATER				to removal of wastes.		
P. DAMAGE TO FLORA/FAUNA						
10. FISH KILL	1					
11- CONTAMINATION						
12. NOTICEABLE GOORS)**·			
13. CONTAMINATION OF SOIL						
14. PROPERTY DAMAGE						
IS. FIRE OR EXPLOSION						
16. SPILLS/LEAKING CONTAINERS/						
17. SEWER, STORM						
10. EROSION PROBLEMS						
10. INADEQUATE SECURITY						
20. INCOMPATIBLE WASTES						
21. MIDNIGHT DUMPING						
2 2. OTh m.' (specify):						
				4.		

EPA Form T2070-2 (10-79)

PAGE 3 OF 4

Continue On Reverse

		VII. PERMIT INFO	DRMATION
A. INDICATE ALL APPLICABLE PER			
4. AIR PERMITS S. LOC	C PLAN X	3. STATE PERMIT 6. RCRA TRANSPO 9. RCRA DISPOSE	·
X 10. OTHER (specify): TDWR S	olid Waste	Registration	No. 32248 -
1. YES 2. NO		3. UNKNOWN	
4. WITH RESPECT TO (list regul		PAST REGULATO	DEV ACTIONS
X A. NONE S. YE	S (summerize below		
	IX. INSPE	CTION ACTIVITY	(past or on-going)
A. NONE X B. YES	(complete items 1,	2,J. & 4 below)	
1. TYPE OF ACTIVITY	2 DATE OF PAST ACTION (mo., day, & yr.)	3 PERFORMED 8Y: (EPA/State)	4. DESCRIPTION
Prehearing Inspection	9/16/74	TDWR District 4	Sludges in "west" lagoon being removed
Annual Compliance Insp.	1/14/76	TDWR District 4	No noncompliances reported
Annual Compliance Insp.	9/30/77	TDWR District 4	No moncompliances reported -
	X. REM	EDIAL ACTIVITY	(past or on-going)
A. NONE B. YES	(complete items I,	, 2, 3, & 4 belaw)	
1. TYPE OF ACTIVITY	2. DATE OF PAST ACTION (mo., day, & yo)	3. PERFORMED SY: (EPA/State)	4. DESCRIPTION .
Excavation/contract disposal	1975-76	Owner	Electroplating sludge wastes in lagoons was removed by private contractor to
		S	permitted facility.
)			
	Wallet Balling Co. Son Till		

EPA Form T2070-2 (10-79)

PAGE 4 OF 4

ATTACHMENT A

POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION AND PRELIMINARY ASSESSMENT SUPPLEMENT SHEET

Instruction - This sheet is provided to give additional information in explanation of a question on the form T2070-2.

Corresponding number on form

Additional Remark and/or Explanation

III-C

V-C


Area of Site: Approximately $60' \times 200' = 12,000 \text{ ft}^2 = 2.8 \text{ acres.}$

Waste information: The CERCLA self-notification form indicated that from 1966 to 1975, electroplating wastewater treatment sludge was disposed in the two parallel surface impoundments. Each impoundment had approximate dimensions of $200^{\circ}x25^{\circ}x6^{\circ}$.

The file records indicate that the TDWR water quality permit of 1975 required that the lagoons be dredged out and replaced with clean fill. This was done in the first quarter of 1976, with the waste and contaminated soil transported to an approved landfill (Walnut Hill site in Dallas).

Permeability data from soil borings taken in the area indicate subsoils of very low hydraulic conductivity (10^{-7} to 10^{-10} cm/sec).

A visit to the site revealed that the area has received fill dirt to grade level and a vegetative cover, and that a fence no longer encloses the area.





Photographer / Witness

Bob Davis

11088

Date / Time / Direction
November 1983

comments: Avea ouce occupied by parallel settling lagoons. Note www trust facilities in bkgd and outful to sewer in freeground. Main plant is on left.

Photographer / Witness

Bob Davis

11088

Date / Time / Direction
November 1983

Comments: Area once occupied by Parallel settling legeons. Note www truit facilities in bkgd and drive entrance in freezewed.

Photographer / Witness

Date / Time / Direction

Comments:___

* 45

ļ_; .

F_